

# LEAK SEALING KNOW HOW *IN ACTION*



## ON – LINE LEAK ARRESTING OF STEAM LINE

### CUSTOMER

THERMAX LIMITED, MAHARASHTRA, INDIA

### APPLICATION DATE

DECEMBER'2011

### APPLICATION SITUATION

Main inlet F W Flange Joint Line

### PROBLEM

Gasket failure, plant could not take shut down due to heavy production loss.

### PRODUCTS

B F W Range Sealing Compound.

### SUBSTRATE

Hardened M S Boiler plate

### APPLICATION METHOD

After correct measurement taken, Clamp was fabricated and installed.

Then Leak sealing compound was injected till finally leak was arrested.



### LEAK SEALING FACT

Due to the quick response, leak was arrested On-Line and this saved the plant valuable time and production

### PICTURES

1. Leakage
2. Clamp fitted and injection in progress
3. Leakage finally arrested