

Know –How *in Action*

BELZONA RECLAIMS VESSEL MONKEY ISLAND DECK

CUSTOMER

VanOord India Pvt Ltd, Mumbai, India

APPLICATION DATE

March' 2011

APPLICATION SITUATION

Deck roof above vessel control room

PROBLEM

Rain water leakage through corroded and holed pitted areas resulting in short circuiting control room computers and equipments

PRODUCTS

Belzona 1311 Ceramic R-Metal

Belzona 3121 MR-7

Belzona 9331 MR-7 Reinforcing tape

SUBSTRATE

Carbon Steel

APPLICATION METHOD

Damaged areas were thoroughly cleaned, and pitted areas were rebuilt with Belzona 1311. Then application of Belzona MR-7 along with Belzona 9331 Reinforcing tape was applied.

BELZONA FACT

Vessel had lost valuable time and money in repairs. But after opting for Belzona and two monsoon periods, the customer is happy with the results.

PICTURES

1. Damaged deck roof area.
2. Corroded pitted areas filled up.
3. Belzona MR-7 coating in progress.
4. Completed application.

