

CASE HISTORY

Title

On Site Machining
Service in Thermal
Power – 660 MW

Customers location

Jay Pee Nigrie STPP,
Satna, MP – L&T
MHI

Execution Date

January 2013

Machining On

LP Turbine Outer
Casing Gland Face

Problem

Misalignment of
Faces in between
Lower and Upper
Casing s

Machine Used

Furmanite SILK ID
Mounted Flange
Facer

Substrate

Special Alloy Steel

