

Case History

Title

On Line Sealing Service -
460 MW Power Plant

Customers

Meghnaghat,
Bangladesh

Execution Date

January 2011

Leakage Parameter

Super Heated Steam
Leakage from Hot Re-
heater Line Crack
Pressure- 110 bar. Temp-
600°C

Application

With the help of
Fabricated Box Clamp
Sealing Compound
Injected- 2H

